

<b>Document Name</b>		Setup of the 56k voice internal PCI (2884A)	
<b>Document Type</b>		Install	
<b>Product or Technology related</b>		56k voice internal PCI (2884A)	
<b>Document Number</b>	EMEA CSO 0004	<b>Document Date</b>	05/07/01

## **Setup of the 56k voice internal PCI (2884A)**

Should you experience any problem installing the 56k voice internal PCI (2884A), please follow the procedure below:

Step one: **Do NOT put the card** inside the computer. Instead, insert CD ROM into the CD-drive, and let the automatic setup install the appropriate drivers.

Step two: Shut down the computer, install the card and restart the computer. At this point the PC, should detect the card properly, find and load the drivers.

At this point, you may be queried for an install disk (i.e. "Winmodem Installation Disk") if so, please specify the relevant folder from the list below:

<b>Operating System</b>	<b>Folder</b> (assuming D: is the drive letter of your CDROM Drive)
Windows 95, 98 and Millennium	D:\Win_9x
Windows NT	D:\NT4\802884A
Windows 2000	D:\Win_2000

For more information, please visit us at <http://www.usr-emea.com/>.